# JONSBO
For your real needs

CR-401
User´s Manual

**A** CPU heat sink

B tieline


C Washer   **D** Positioning Screw   **E** Stand-off

F Bracket Screw   **G** Intel Bracket   **H** AMD Bracket

**I** hex nut   **J** Thermal Grease   **k** Wrench


L Back Plate

Step 1

EN	Place INTEL bracket on the cooler base, and then use bracket screws to fix it.
CN	将INTEL支架安装到散热组上，并用螺丝拧紧。

Step 2

螺母朝上 nut facing up

螺杆装入扣具对应方向
Install threaded rod to the corresponding direction of the buckle

LGA775
LGA115X
LGA1366

| EN	Install threaded rod to the corresponding holes of INTEL bracket as needed, fixing it with nut facing up.
CN	根据需要将螺杆装入INTEL对应孔位内，将隔套内螺母朝上拧紧固定。

Step 3

J

EN	Apply the thermal grease evenly on to the CPU surface. Remove the protective film from the cooler base.
CN	将散热膏均匀地涂抹在CPU表面上，并取下散热器座上的保护贴膜。

Step 4

C

EN	Pointing the holes of the motherboard to the poistioning screws of the cooler ,and then assemble them together,install insulating washers.
CN	将主板孔位对准散热器定位螺丝，反扣于散热组上，装入绝缘垫片。

Step 5

L

EN	Install back plate(as shown in the figure)
CN	装入背板（如图所示）。

Step 6

I   **k**

EN	Fix the coolers on the motherboard by fixing the hex nuts with the wrench.
CN	用开口板手拧紧六角螺母，将散热组固定到主板上。

Step 7

CPU FAN

EN	Connect the CPU fan to the motherboard
CN	将CPU风扇导线与主板连接。